

CHRYSLER CROSSFIRE TSB's FROM 2003 TO 2006

2003 LIST

08-018-03 ELECTRICAL INFORMATION AND GENERAL INFORMATION 2003-06-13
08-029-03 REPLACEMENT KEYS 2003-10-24
08-036-03 RADIO DISPLAY HARD TO READ IN BRIGHT SUNLIGHT 2003-12-12
19-005-03 POWER STEERING FLUID USAGE - REVISED 2003-08-29
21-009-03 AUTOMATIC TRANS DIAGNOSTIC TEARDOWN PROCEDURE 2003-08-29
22-004-03 CHROME WHEEL CARE 2003-09-26
23-023-03 WIND-LIKE SOUND MIRROR FLAG AREA ABOVE 50 MPH 2003-10-17
24-003-03 A/C SYSTEM ADDITIVES 2003-05-23

2004 LIST

02-008-04 RATTLE SOUND FROM REAR SHOCKS 2004-11-08
02-009-04 SQUEAKING SOUND FROM FRONT SUSPENSION 2004-12-16
04-043-04 HEADLAMP CONDENSATION 2004-12-18
08-030-04 KEYLESS ENTRY TRANSMITTERS DO NOT WORK 2004-09-02
21-002-04 FIRST GEAR SYNCHRONIZER ENHANCEMENTS 2004-03-09
23-014-04 WIND SOUND WHILE DRIVING 2004-05-04
23-019-04 RATTLE SOUND FROM LIFTGATE AREA - REVISED 2004-07-28
23-025-04 SQUEAK/CREAK NOISE COMING FROM REAR SPOILER
23-040-04 REAR SPOILER SERVICE PARTS AND PROCEDURES 2004-10-05
23-042-04 DECKLID WILL NOT OPEN 2004-10-18
23-047-04 WIND SOUND MIRROR FLAG AREA ABOVE 50 MPH REVISED 2004-11-11
23-051-04 LIFTGATE BUMPER FASTENER WILL NOT TIGHTEN 2004-12-06
25-001-04 EVAPORATIVE SYSTEMS MAINTENANCE 2004-11-22

2005 LIST

08-002-05 HEADLAMP CONDENSATION - REVISED 2005-01-13
08-009-05 PNEUMATIC LOCK HOSE REPAIR KIT AVAILABLE 2005-02-05
08-015-05 POWERTRAIN CONTROL MODULE INITIALIZATION 2005-03-02
21-001-05 GEAR GRIND LIKE SOUND WHILE SHIFTING 2005-01-06
21-002-05 AUTOMATIC TRANSMISSION FLUID WEEPAGE 2005-01-14
21-005-05 FIRST GEAR SYNCHRONIZER ENHANCEMENTS - REVISED 2005-02-05
23-001-05 POPPING SOUND FROM THE SIDE WINDOW AREA 2005-01-08
23-004-05 DOOR GLASS MISALIGNMENT OR CONTACTS THE ROOF 2005-01-28
23-016-05 CENTER CONSOLE CUP HOLDER/STORAGE BIN EXCHANGE 2005-03-09
23-019-05 CONVERTIBLE TOP DIFFICULT TO CLOSE 2005-03-16
23-022-05 LOW GLOSS INTERIOR TRIM - MAINTENANCE 2005-04-02

2006 LIST

08-003-06 INSTRUMENT CLUSTER INITIALIZATION 2006-01-18
08-030-06 POWERTRAIN CONTROL MODULE INITIALIZATION - REVISED 2000-08-25
23-032-06 REAR SPOILER SERVICE PARTS AND PROCEDURE 2006-07-29
23-036-06 INSIDE DOOR HANDLE SERVICE PARTS AVAILABLE 2006-11-06

UNOFFICIAL RECALL CAMPAIGNS "CUSTOMER SATISFACTION NOTIFICATION"

RC-D11 RADIATOR INLET HOSE 2004-04
RC-E19 RADIATOR COOLING FAN REVISED 2006-03